

INDEPENDENT

🗳 DATA DRIVEN



Order ID : 194723

28 Sep 2019



Automobile from dealer in good condition is valued at **Rs. 10,18,196 - Rs. 10,81,177** 

| Toyota Corolla Altis 2016 1.8 G                                  |   | Vehicle Price in All Conditions                            |  |
|--|---|--|--|
|  |   | FAIR<br>Rs.9,92,741 - Rs.10,54,148                         |  |
|  |   | VERY GOOD<br>Rs.10,43,651 - Rs.11,08,207                   |  |
|  |   | EXCELLENT<br>Rs.10,69,106 - Rs.11,35,236                   |  |
|  | 000   |  |  |
| 4  | <b>A</b> 76,000 🛱 2016  |  |  |
| Vehicle De   |   | Advanced Evaluation Conditions                             |  |
|  |   | Advanced Evaluation Conditions                             |  |
| Vehicle De   | tails   | GOOD<br>Transmission, Suspension, Steering, Frame, Engine, |  |
| <b>Vehicle De</b><br>Make  | <mark>tails</mark><br>Toyota  | GOOD   |  |
| <mark>Vehicle De</mark><br>Make<br>Model                         | <mark>tails</mark><br>Toyota<br>Corolla Altis                           | GOOD<br>Transmission, Suspension, Steering, Frame, Engine, |  |
| <mark>Vehicle De</mark><br>Make<br>Model<br>Year                 | <mark>tails</mark><br>Toyota<br>Corolla Altis<br>2016                   | GOOD<br>Transmission, Suspension, Steering, Frame, Engine, |  |
| <mark>Vehicle De</mark><br>Make<br>Model<br>Year<br>Trim         | tails<br>Toyota<br>Corolla Altis<br>2016<br>1.8 G                       | GOOD<br>Transmission, Suspension, Steering, Frame, Engine, |  |
| Vehicle De<br>Make<br>Model<br>Year<br>Trim<br>KM Driven         | tails<br>Toyota<br>Corolla Altis<br>2016<br>1.8 G<br>76,000 kms         | GOOD<br>Transmission, Suspension, Steering, Frame, Engine, |  |
| Vehicle De<br>Make<br>Model<br>Year<br>Trim<br>KM Driven<br>City | tails<br>Toyota<br>Corolla Altis<br>2016<br>1.8 G<br>76,000 kms<br>Pune | GOOD<br>Transmission, Suspension, Steering, Frame, Engine, |  |

#### Disclaimer





| ORANGE BOOK VALUE<br>Resale ka MRP  | India's Firs | t & Only Algorithmic Pricing En            |   | Cortrincato                          |  |  |
|-------------------------------------|--------------|--|---|--------------------------------------|--|--|
|                                     |              |  |   | Order ID: 194723<br>28 Sep 2019      |  |  |
| New V<br>Price N<br>Rs. 19,28,      | Now          | New Vehicle<br>Price Then<br>Rs. 17,44,529 | Total Cost of<br>Ownership<br>Rs. 16,78,243 | What Others<br>Paid<br>Rs. 16,29,000 |  |  |
| Next 3 Year Depreciation of Vehicle |              |  |   |                                      |  |  |
| Estimated Buying Price From Dealer  |              |  | Estimated Selling Price To                  | Dealer                               |  |  |
| 2020                                |              | Rs.9,81,762                                | 2020  | Rs.8,83,605                          |  |  |
| 2021                                |              | Rs.8,95,983                                | 2021  | Rs.8,06,402                          |  |  |
| 2022                                |              | Rs.7,97,832                                | 2022  | Rs.7,18,065                          |  |  |

# Disclaimer








independent

DATA DRIVEN




#### Order ID : 194723

28 Sep 2019



#### Similar Listings for Past 90 Days

Similar Listings for Past 90 days



# Similar Listings for Lifetime

Similar Listings for Lifetime



#### Similar Orders for Past 60 days 1 750k Rs. 1435500 Rs. 1434500 1 500k Rs. 1321523 1 250k Rs. 1120480 1 000k 750k 500k 250k 0k Mean Median High Low

### Similar Orders for Past 90 Days


Similar Orders for Past 60 Days

Similar Orders for Past 90 days



# Similar Orders for Lifetime

Similar Orders for Lifetime



# Disclaimer







India's First & Only Algorithmic Pricing Engine for Used Automobiles

independent 🖓 Unbiased

🔗 DATA DRIVEN



Order ID: 194723 28 Sep 2019

# **Component Health Check**

A vehicle undergoes enormous wear and tear with time. It is often imperative to inspect and replace parts of the vehicle on a timely basis to keep it in prime condition. These aspects often go unnoticed and become real pain points with time. Use the Component Health Check for maintaining your vehicle components without any hassles. It would provide the list of parts to be inspected every subsequent year based on their age to help you find out the parts needing replacement.



#### Disclaimer







Order ID: 194723 28 Sep 2019

#### Glossary

New Vehicle Price Now: This provides the current On-Road Price of a new vehicle of the same Make-Model-Trim

**New Vehicle Price Then:** This provides the On-Road Price of the vehicle at the time it was purchased in brand new condition.

**Total Cost of Ownership:** This provides the total cost of owning this vehicle which includes the cost of running this vehicle and its maintenance cost over the next 5 years

**What Others Paid:** This provides an estimated value of the price paid by others for a similar used vehicle. However, the final valuation provided might vary based on the city, condition of the car and many other factors.

**Next 3 Year Depreciation of the Vehicle:** This provides an estimated price that your used vehicle would fetch or an estimated price that you would have to pay for a similar vehicle over the next 3 years.

**Similar Listings for Past 60 days/Past 90 days/Lifetime:** This provides some data points regarding similar vehicles that have been listed on Droom in the respective duration. Low and High provide the Lowest and the Highest Values Quoted for similar vehicles whereas Mean and Median indicate the average and median values.

**Similar Orders for Past 60 days/Past 90 days/Lifetime:** This provides some data points regarding similar vehicles that have been sold on Droom in the respective duration. Low and High provide the Lowest and the Highest Values at which similar vehicles have been sold whereas Mean and Median indicate the average and median values.

**Component Health Check:** This provides a list of parts that are advised to be inspected every subsequent year based on their age. This would help you find out the parts needing maintenance/replacement.

#### Disclaimer



